

SOP04819

Generator AGS Harness TRIPLE E Clamping Repair (QAAR9927)

Department: 11: N/A
People Required:

Time to Complete: 00:05:00

Date Created:

Date Revised: Rev #:


00:00:00

Created by Initial: GK/806 Verified: GK806

Page 1 of 1



Locate the generator.



Remove the access door.

ACCUTION PROPERTY AND ADMINISTRATION OF THE PROPERTY ADMINISTRATION OF THE PROPERTY AND ADMINISTRATION OF THE PROPERTY AN

Locate the AGS harness plug on the left hand side of the generator.

Technical Data:

Safe Work Procedures:



Bundle the extra length of wire in the harness with the two nylon ties.

(shown here in white for visibility, these will be black in the repair kit.)



With the black nylon tie straps.

Replace and latch generator access door.

Notes:

6

9

00:00:00

00:00:00

00:00:00

00:00:00

00:00:00

00:00:00

0