

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER				
Safety Recall 69CK	Safety Recall	69CK	What vehicles are included in Safety Recall 69CK?					
				Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
				USA	2020	2021	JETTA	356
				USA	2020	2021	JETTA GLI	23
			What is the safety concern for Safety Recall 69CK?	During rework at the factory, the airbag control module fixation holes were enlarged in order to allow correct assembly to the vehicle body. Because of this, the airbag may not deploy correctly in a crash, or may deploy unintendedly while driving, leading to an increased risk of injury.				
			Are there any precautions I should take because my vehicle is part of Safety Recall 69CK?	If there is an issue with the airbag control module, the airbag malfunction indicator light will illuminate. Owners are advised to contact an authorized dealer without delay to have the vehicle inspected if the airbag light illuminates, and also to ensure they are familiar with the airbag system information in the owner's manual.				
			What is the repair for Safety Recall 69CK?	Replace the airbag control module and also replace an incorrectly positioned airbag control module mounting stud.				
			When will the repair for Safety Recall 69CK be available?	Repairs for this recall have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer .				