



May, 2022

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2020 Ranger has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **21C24 - Child Restraint RAP Cab rear ISOFIX**

What is the issue? On your vehicle, the rear seat head restraints may interfere with proper installation of certain taller child seats. Additionally, the lower rear child seat anchorages on your vehicle may be improperly aligned which may increase the difficulty to install a child seat with rigid anchor attachments.

If a child seat is not properly installed, it can increase the risk of injury in a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Mayo de, 2022

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2020 Ranger las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **21C24 - ISOFIX trasero de asiento de seguridad para niños RAP Cab**

¿Cuál es el problema? Las cabeceras del asiento trasero de su vehículo podrían interferir con la correcta instalación de algunos asientos para niños más altos. Adicionalmente, los anclajes inferiores traseros del asiento para niños de su vehículo podrían estar incorrectamente alineados, lo cual podría aumentar la dificultad para instalar un asiento para niños con conexión de anclaje rígido.

Si un asiento para niños no está correctamente instalado, el riesgo de sufrir lesiones en caso de choque aumenta.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0003668 A / 000000000000145 / 145



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

