OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-791

Manufacturer Name: HME, Inc.
Submission Date: OCT 12, 2021
NHTSA Recall No.: 21V-791
Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: HME, Inc.

Address: 1950 Byron Center Ave.

Wyoming MI 49519

Company phone: 616-534-1463

Population:

Number of potentially involved: 1 Estimated percentage with defect: 100 %

Vehicle Alterer Information:

Vehicle 1: 2014-2014 Ford F-550

Descriptive Information: The Ford F550 on-board diagnostic system may not illuminate the malfunction

indicator light (MIL) on the dashboard to alert the operator when certain faults

are present in your vehicle's emissions control system.

Production Dates: JUN 06, 2013 - OCT 18, 2013

Description of Defect:

Description of the Defect: The Ford F550 on-board diagnostic system may not illuminate the malfunction

indicator light (MIL) on the dashboard to alert the operator when certain faults

are present in your vehicle's emissions control system.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the emissions control system is not functioning properly, exhaust emissions

may be elevated while in operation, and the vehicle's diagnostics system might not be able to alert the operator of the fault. Once the vehicle's powertrain control module (PCM) is reprogramed with the updated calibration, the diagnostic system will detect if your nitrogen oxides (NOx) sensors and the catalytic converter portion of the selective catalyst reduction (SCR) system are funtioning properly. A malfunction indicator light (MIL) will later be displayed on the dashboard panel if the NOx sensors or SCR is

not functioning properly.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR NR

Country: NR

Chronology:

NR

Description of Remedy:

Description of Remedy Program: NR How Remedy Component Differs NR

from Recalled Component :

Identify How/When Recall Condition NR was Corrected in Production :

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Part	573	Safety	Recall	Report
------	------------	---------------	--------	--------

21V-791

Page 3

Name : Address :

Country : Company Phone :

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573