#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## **22E-013**

**Manufacturer Name:** Comoto Holdings, Inc.

Submission Date: FEB 23, 2022 NHTSA Recall No.: 22E-013

**Manufacturer Recall No.:** NR



#### **Manufacturer Information:**

Manufacturer Name: Comoto Holdings, Inc.

Address: 4020 S 26th St

Philadelphia PA 19112

Company phone: 2156932191

## **Population:**

Number of potentially involved: 33,869 Estimated percentage with defect: NR

## **Equipment Information:**

Brand / Trade 1: BILT HELMET

Model: AMPED EVO ADULT

Part No.: BLH126
Size: MD, XL, 2XL
Function: Head Protection

Descriptive Information: A few helmets failed to comply during DOT testing. Penetration test failure and a

2nd impact dwell time test failure Quantity potentially involved 18,157

Production Dates: MAY 01, 2019 - JUL 01, 2021

Brand / Trade 2: BILT HELMET

Model: BILT AMPED EVO YOUTH

Part No.: BLH127
Size: SY, MY, XLY
Function: Head Protection

Descriptive Information: A few helmets failed to comply during DOT testing. Penetration test failure.

Quantity potentially involved 14,338

Production Dates: MAY 01, 2019 - JUL 01, 2021

Brand / Trade 3: BILT HELMET

Model: BILT AMPED EVO RAPID ADULT

Part No.: BLH142

Size: MD, LG, 2XL, 3XL

Function: NR

Descriptive Information: A few helmets failed to comply during DOT testing. Penetration Test Failure.

Potential quantity involved 1,374

Production Dates: JUL 01, 2021 - JUL 31, 2021

## **Description of Noncompliance:**

Description of the Penetration test failure and a 2nd impact dwell time test failure

Noncompliance:

FMVSS 1: 218 - Motorcycle helmets

FMVSS 2: NR

Description of the Safety Risk: Penetration test failure: Very rare safety risk

2nd impact

dwell time test failure: Not a safety risk

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

#### **Involved Components:**

Component Name: NR

Component Description: NR

Component Part Number: NR

### **Supplier Identification:**

#### **Component Manufacturer**

Name: Nexports Corporation Ltd

Address: Room 706, Yijian Building

No 3 Jiansheliu Road, Yuexiu District Guangzhou, Guangdong Foreign States

Country: China

## **Chronology:**

**3rd Party Testing** 

## **Description of Remedy:**

Description of Remedy Program: Will provide owners of the recalled helmets with either. 1) a replacement

BILT model helmet which complies with FMVSS 218; or 2) other model helmet of equal or lesser value; or 3) aa credit with an additional 10%

discount:

How Remedy Component Differs Helmets manufactured in the last 3 years

from Recalled Component:

Identify How/When Recall Condition N/A

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date : FEB 22, 2022 - FEB 22, 2022 Planned Owner Notification Date : FEB 23, 2022 - APR 24, 2022

#### **Purchaser Information:**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

\* NR - Not Reported