

August 19, 2022

Mr. Tony Sappington Manager- Product Safety Iowa Mold Tooling Co., Inc. 520 Hwy St E Dodge Center, MN 55927

Subject: Stabilizer Beam Welds May Crack Over Time

Dear Mr. Sappington:

This letter serves to acknowledge Iowa Mold Tooling Co., Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: IMT/42684/9999

Mfr's Report Date: August 15, 2022

NHTSA Campaign Number: 22E-067

Components: EQUIPMENT

Potential Number of Units Affected: 32

Problem Description:

Iowa Mold Tooling Co., Inc. (IMT) is recalling certain Hydraulic Loaders, model 42684 and part number 6390121. The welds on the stabilizer beams may crack over time, or break under load.

Consequence:

A cracked or broken stabilizer beam can cause the vehicle to tip, or disengage the load, increasing the risk of injury.

Remedy:

Dealers will replace the stabilizer beams, free of charge. Vehicle manufacturers are expected to be notified September 2, 2022. Owners may contact IMT customer service at 1-877-751-4222. IMT's number for this recall is TB2022001-IMY dist.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107KL 22E-067

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Iowa Mold Tooling Co., Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alare Andy

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

