

Part 573 Safety Recall Report

22T-014

Manufacturer Name : PT. Elangperdana Tyre Industry

Submission Date : MAY 18, 2023

NHTSA Recall No. : 22T-014

Manufacturer Recall No. : Not applicable.



Manufacturer Information :

Manufacturer Name : PT. Elangperdana Tyre Industry

Address : Jl. Elang, Desa Sukahati, Citeureup
Bogor West Java Bogor West Java 00
16810

Company phone : 999

Population :

Number of potentially involved : 31,500

Estimated percentage with defect : 100 %

Tire Information :

Tire Brand 1 : Zeetex AT 1000

Tire Line : Light Truck

Tire Size : LT245/75R17 and 4 other sizes

Descriptive Information : The entire population of Zeetex AT 1000 size LT 245/75R17 imported into the U. S.

Production Dates : NOV 02, 2014 - JUN 12, 2022

TIN (Tire Identification Number)

Plant ID	Size code	Optional Code	Begin M Code	End M Code
109	45/75R17	NR	7842	7842

Description of Defect :

Description of the Defect : Premature sidewall separation near the bead area

FMVSS 1 : 139 - New pneumatic radial tires for light vehicles

FMVSS 2 : NR

Description of the Safety Risk : Premature failure of the subject tire which may cause personal injury, property damage or even death.

Description of the Cause : Under investigation. Probable causes include faulty design, compound, or deficiency in manufacturing process.

Identification of Any Warning that can Occur : Unusual vibration of the vehicle or noise from the tire or vehicle.

Involved Components :

Component Name : Not applicable

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Not applicable.

Address : NR

NR

Country : NR

Chronology :

Receipt of a letter dated June 22, 2022 from NHTSA stating its compliance test revealed sidewall separation near the bead area. Tire tested was only for LT245/75R17. Upon inquiry from NHTSA if there is only one size of the recalled tire, 4 more sizes were added to the recall based on further investigation of all other sizes bringing the total recalled tires to 5 sizes. Please refer to Attachment #1

Description of Remedy :

Description of Remedy Program : Recall for monetary compensation. Please refer to Attachment #2.

How Remedy Component Differs from Recalled Component : Not applicable

Identify How/When Recall Condition was Corrected in Production : Upon receipt of NHTSA letter of 6/22/2022 production of all Zeetex/ AT1000 line of tires regardless of size stopped. Then the design, engineering specs and compound formula had been reviewed and improvements has been made to all. The so improved tires have been sent to reputable third party test lab to ascertain compliance with all applicable FMVSS standards. Results of such third party compliance test were sent to NHTS for its review and approval. Please see Attachment #3

Recall Schedule :

Description of Recall Schedule : All notification to dealers and owners were mailed from 9/12/2022 and completed by 9/30./2022. Please see Attachment #4 for a copy of letter to dealers and Attachment #5 for a copy notification to owners.

Planned Dealer Notification Date : SEP 12, 2022 - SEP 30, 2022

Planned Owner Notification Date : SEP 12, 2022 - SEP 30, 2022

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : Not applicable.

Address : NR

00

Country : NR

Company Phone : NR

* NR - Not Reported