



INSTRUCTIONS TO PERFORM RECALL CAMPAIGN 166

Models Affected:

Certain Model Year Winnebago Certain 2021-2023 Ekko (622A) Motorhomes.
These motorhomes were manufactured from January 8, 2021, through April 27, 2022.

Tools Required:

- Tool to cut LP hose
- Digital Camera

Procedure:

1. Record and Verify the Serial Number of the coach is affected by recall 166.
2. Prior to giving the customer his new replacement hose. Take possession of the original hose assembly that came with his coach.
3. Customer is free to go.
4. Take the original hose received from the customer and cut the hose in half.
5. Take a digital photo showing that the hose was cut in two.
6. Discard/Scrap both parts of the hose.
7. Send in the digital photo with the completed warranty reimbursement claim.

