

Advance Notice – Safety Recall 19Q8 / Radiator and Coolant Hose

This notice is for: Date: Issue:	 Dealer Principal General Manager Parts Manager Parts Manager Sales Managers Service Consultant September 30, 2022 During vehicle production, the radiator may not have been affixed correctly to the intercooler. This can result in the radiator becoming loose and causing a coolant hose to contact the V-belt pulley. A coolant hose that contacts the V-belt pulley can become damaged, potentially resulting in a coolant leak. A large amount of coolant leaking onto the roadway may increase the risk of a crash for the following traffic. If the red warning light in the instrument cluster is ignored and the vehicle continues to be driven without coolant, the engine may overheat, potentially leading to a vehicle fire. 					
Precautions:	If a low coolant level is detected, the driver will see a red warning light in the instrument cluster. Customers with vehicles experiencing this condition are advised to contact an authorized Volkswagen dealer without delay to have the vehicle inspected.					
Repair:	 REPAIR NOT YET AVAILABLE Check daily campaign open inventory report or OMD for affected vehicles in inventory. 					
		Beginning	Ending			
Affected Vehicles	Country	Model Year	Model Year	Vel	hicle	Vehicle Count
Affected venicles	Country					Count
Affected Venicles		Year	Year	GOL	hicle .F GTI /LF R	Count 6,632
Affected Venicles	USA	Year 2022	Year 2023	GOL GO	.F GTI	Count
Affected Venicles	USA USA	Year 2022 2022	Year 2023 2023	GOL GO GOL	.F GTI LF R	Count 6,632 1,406
Affected Venicles	USA USA CAN CAN *Counts reflect screen in Elsa o	Year 2022 2022 2022 2022 2022	Year 2023 2023 2022 2022 2022 ion; some vehicl ir to verify that a	GOL GO GOL GO es may have already	F GTI LF R .F GTI	Count 6,632 1,406 1,693 784 & Campaigns/Actions
Affected Venicles	USA USA CAN CAN *Counts reflect screen in Elsa of campaign inqui	Year 2022 2022 2022 2022 to overall population the day of repairing the second	Year 2023 2023 2022 2022 2022 ion; some vehicl ir to verify that a source.	GOL GO GOL GO es may have already VIN qualifies for rep	.F GTI LF R .F GTI LF R 9 been repaired. Check	Count 6,632 1,406 1,693 784 & Campaigns/Actions Elsa is the <u>only</u> valid

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.