

IMPORTANT SAFETY RECALL

(NHTSA Recall Number: 22V836) This notice applies to your vehicle: (Insert VIN)

January 9, 2023

Dear Kia Niro Vehicle Owner:

Kia has identified a defect in your vehicle which relates to motor vehicle safety.

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Kia America, Inc. has decided that a defect which relates to motor vehicle safety exists in certain 2017-2018 MY Niro Hybrid vehicles. The defect may cause heat damage to the rear seat, increasing the risk of a fire. Our records indicate that you own or lease one of the potentially affected vehicles.

On November 23, 2018, a different recall notice (18V666 or Kia's Reference # SC168) was sent to vehicle owners regarding the Power Relay Assembly (PRA). This is a new recall and supersedes the previously launched 18V666 recall.

What Is The Problem?

The Power Relay Assembly (PRA) is located underneath the rear seat of your vehicle and consists of various components including the Main Relay. Inadequate connection between the Main Relay contacts can increase electrical resistance, thereby generating heat. If sufficient heat is generated, thermal damage may occur to the rear seat, increasing the risk of a fire. Recall 18V666 addresses this concern by instructing dealers to inspect and replace the PRA if thermal damage is found or replace the Main Relay if no thermal damage is found. However, your vehicle may not have had the remedy relay installed during the 18V666 recall repair. As a result, the potential for a fire may still exist.

Kia Will Inspect And, If Necessary, Replace The Power Relay Assembly or The Main Relay Free of Charge At No Cost To You.

Kia dealers will inspect the Power Relay Assembly (PRA) for any signs of thermal damage. If any thermal damage is present, the PRA will be replaced with a new one. If no thermal damage is present and the original Main Relay is still installed, the Main Relay will be replaced with a new one. This recall will be performed **free of charge at no cost to you.** The estimated time required to perform the recall will be approximately one (1) to two (2) hours. We recommend scheduling a service appointment to minimize your inconvenience.

What Should You Do?

- WARNING: Do not install a Child Safety Seat on the rear left passenger seat until the recall has been completed.
- In the interest of the safety of your passengers, as well as your own safety, please immediately contact your authorized Kia dealer to arrange for the recall repair to be performed on your vehicle.
- The illumination of the HEV warning light while driving and/or the inability to start the vehicle may be an indication of this concern. If either of these conditions occurs, contact Kia Roadside Assistance at 1-800-333-4542 or online at kia.rsahelp.com to request to have your vehicle towed to the nearest authorized Kia dealership as soon as possible.

• To find your nearest dealer, visit <u>www.kia.com</u> and click the "Find Dealer" button in the upper right corner ("Dealers" on a mobile device). You can also use the QR code below with your mobile device to access this information *(see the bottom of this letter for more information about QR code use)*:



What If You Have Already Paid To Have This Situation Corrected?

If you have incurred expense to remedy this issue prior to the date of this notice, you may have the opportunity to obtain reimbursement for that expense. You may submit your receipts online to Kia via the Owners section of <u>www.kia.com</u> or mail your receipts with a copy of the attached Request for Reimbursement form directly to Kia for review and consideration:

Kia Customer Care Center Kia America, Inc. P.O. Box 52410 Irvine, CA 92619-2410 1-800-333-4542

Pursuant to the General Reimbursement Plan issued by Kia pursuant to Federal Regulation 49 CFR 573.13, Kia will use its best efforts to respond to your claim within sixty (60) days of receipt and at that time Kia may either accept or reject that claim or it may request more information to evaluate the claim.

Have You Changed Your Address Or Sold Your Kia?

If you have changed your home address, sold your Kia vehicle, or no longer own your vehicle, please complete the attached prepaid "Change of Address/Ownership" card and mail it to us. You can also contact the Kia Customer Care Center phone number listed above.

What If You Are A Vehicle Lessor?

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

What If You Have Other Questions?

If your dealer does not respond to your service request in a timely manner, we suggest that you call Kia's Customer Care Center at 1-800-333-4542. This number has TTY capability. If you still are not satisfied that we have remedied this situation without charge and within a reasonable amount of time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

This action has been taken in the interest of your safety, and we regret any inconvenience this situation may cause you.

Sincerely,

Customer Care Department

QR Code Use:

- A QR Code is a square, 2-dimensional barcode that can be read by mobile devices loaded with an appropriate barcode or QR Code Reader App. The app reads the barcode image and then launches/uploads the specific information the code contains, such as URLs, text, photos, videos.
- With a mobile device, download a QR Code Reader App. With many devices, you can do this through an app store or marketplace.
- Open the QR Code Reader App on your mobile device. The app will utilize your device's camera. Center the code in the camera viewing area. With some apps, the URL or other information will automatically load when the code is recognized. For others, you may have to snap or take a picture of the QR code. Refer to the QR Reader Code App instructions.

REQUEST FOR REIMBURSEMENT FORM 2017-2018 MY NIRO HYBRID VEHICLES - POWER RELAY ASSEMBLY (PRA) SAFETY RECALL CAMPAIGN (SC256)

If you have incurred expense to remedy this issue prior to the date of this notice, you may have the opportunity to obtain reimbursement for that expense. You may <u>submit your receipts online to Kia via the Owners section of www.kia.com</u> (MyKia>Contact Us or directly at this link: <u>https://ksupport.kiausa.com/ConsumerAffairs</u>).

If you do not have access to a computer or prefer to submit your request by mail, please complete this Request for Reimbursement and mail it to the following address for review and consideration, along with backup documentation:

Kia Customer Care Center Kia America, Inc. P. O. Box 52410 Irvine, CA 92619-2410 1-800-333-4542

Please allow at least sixty (60) days for review and response.

Customer First Name:					Custor	mer l	_ast N	ame:								
Customer Address:																
Customer City:					State:				Zip	:						
Phone #: ()	-			Email:											
Vehicle Identification N	umber:															
Mileage at Time of Repair:				Date of Repair: / /												
Amount of Reimbursement Requested																

Attach the following:

- Repair Order showing:
 - Name & address of person paying for the repair
 - Vehicle Identification Number (VIN) of vehicle repaired
 - Description of the problem repaired
 - Date of repair, mileage at the time of repair and total cost of claimed repair expense
- Evidence of Payment of Repair showing:
 - Date of Payment
 - Amount Paid (e.g., copies of cancelled check or credit card receipt)

I certify that the documents attached to this Request for Reimbursement are true and accurate and should be used as the basis for a reimbursement to me under this campaign.

CLAIMANT'S SIGNATURE: