



Navistar, Inc.  
2701 Navistar Drive  
Lisle, IL 60532 USA

navistar.com



A NAVISTAR COMPANY

**IMPORTANT SAFETY RECALL 22522**  
**INTERIM NOTICE**  
**NHTSA RECALL NO. 22V-849**

**JANUARY 2023**

This notice applies to your vehicle identified on the enclosed card.

Dear INTERNATIONAL® Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Navistar has decided that a defect which relates to motor vehicle safety exists in certain 2021 thru 2023 eMV series trucks built 12/08/2020 thru 10/14/2022 with feature codes 0008TLC (210 kWh Total Battery Capacity) or 0008TLD (315 kWh Total Battery Capacity).

**REASON FOR THIS RECALL**

The high voltage positive cables from the battery packs to the Manual Service Disconnects (MSDs) may have incorrect identification marking tape that indicates a lower level 2 isolation (MSD removal) instead of indicating a level 3 isolation (battery fuse removal).

**RISK TO MOTOR VEHICLE SAFETY**

An incorrectly identified cable may indicate to a first responder, technician, or customer that the cable is deenergized, when it may not be, possibly increasing the risk of electrical shock resulting in personal injury or death.

**DEFECT REMEDY**

A final remedy has been determined. Parts have been ordered and will be available in late-January. When parts become available, you will be notified of additional actions you should take.

**ACTIONS YOU SHOULD TAKE**

To minimize the potential risk of this defect in the interim period, please assume all high voltage cables, regardless of identification marking tape colors, can only be deenergized by performing a level 3 isolation (battery fuse removal).

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

**IF YOU NEED FURTHER ASSISTANCE**

Refer to the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

Navistar requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

**Navistar, Inc.**