


RECALL 24V030 / 2024-021 REMEDY INSTRUCTIONS

	Make(s): SHASTA Model(s): MANY, SEE BELOW Model Year(s): 2024	Repair Code: RC-056-01-00-004476 Allotted Time: 1.20 HRS. PER UNIT Inspection Code: N/A Allotted Time: N/A
	Concern: The side marker lamps do not meet F/CMVSS 108 Reflective Requirements.	Photo(s) Required: NO Prior Authorization Required: NO Part(s) Kit Number: F100509025 Part(s) Return: NO

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

CERTAIN 2024 – SHASTA – SST16BH, SST16RE, SST29BH, SST31OK, SST31QB & SST32DS

STEP 1. LOOSEN AND REMOVE THE SNAP-ON LENS FROM THE ORIGINAL LIGHT FIXTURE;

STEP 2. REMOVE THE TWO SCREWS THAT ARE HOLDING THE LIGHT ON

STEP 3. GENTLY REMOVE THE LIGHT BASE FROM THE UNIT.

- CUT AND LOOSEN ANY SILICONE FROM AROUND THE LIGHT FIXTURE BASE TO REMOVE IT;
- CLEAN OFF ANY REMAINING SILICONE FROM THE UNIT;

STEP 4. OPEN THE LEVER ON THE WAGO CONNECTOR HOLDING THE WHITE WIRE FROM THE LIGHT FIXTURE AND REMOVE THE WIRE FROM THE CONNECTOR;

- INSERT THE WHITE WIRE FROM THE NEW LIGHT FIXTURE INTO THE CONNECTOR AND CLOSE THE LEVER;

STEP 5. OPEN THE LEVER ON THE WAGO CONNECTOR HOLDING THE COLORED WIRE FROM THE LIGHT FIXTURE AND REMOVE THE WIRE FROM THE CONNECTOR;

- INSERT THE COLORED WIRE FROM THE NEW LIGHT FIXTURE INTO THE CONNECTOR AND CLOSE THE LEVER;

STEP 6. PRESS THE FOAM GASKET INTO THE BACK OF THE LIGHT BASE UNTIL IT IS COMPLETELY SEATED;

STEP 7. REINSTALL THE NEW LIGHT FIXTURE BASE USING THE ORIGINAL SCREWS;

STEP 8. GENTLY PRESS THE NEW LENS ONTO THE BASE;

STEP 9. SEAL ALL AROUND THE EDGE OF THE NEW LIGHT FIXTURE WITH CLEAR SILICONE

STEP 10. CLAIM REPAIR CODE.