

Product Quality and Service Support, Quality Compliance
Published: September 5, 2018

Toyota Motor Sales, USA, Inc.
6565 Headquarters Drive
Plano, TX 75024
(469) 292-4000

Approved By: Tom Trisdale

Vice President, Product Quality and Service Support

To: All Toyota Dealers
From: Quality Division – Product Quality and Service Support

Safety Recall J0T (Interim J1T) – *Interim Notice*
Certain 2016 – 2018 Model Year Prius
Engine Wire Harness

- Safety Recall J0T (Interim J1T) Dealer Letter now available on TIS.
- When the remedy for Safety Recall J0T (Interim J1T) becomes available, the remedy for the vast majority of the involved vehicles will involve the application of protective tape to a portion of the engine wire harness as described in the remedy procedure instructions.
- Toyota has already started shipping an initial quantity of the protective tape to dealerships via a third party shipping carrier (UPS) and these initial quantities are estimated to arrive on September 5, 2018. Please be alert for the arrival of these tape shipments at your dealership and please keep this tape on-hand until the remedy becomes available.

Example picture of the protective tape:



Refer to the Dealer Letter on TIS for additional information.

Thank you for your cooperation.
TOYOTA MOTOR SALES, U.S.A., INC.