



**NUMBER:** 21-001-15 REV. A

**GROUP:** Transmission and Transfer Case

**DATE:** February 12, 2015

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 21-001-15, DATED JANUARY 10, 2015 WHICH SHOULD BE REMOVED FROM YOUR FILES. THIS IS A COMPLETE REVISION AND NO \*\*ASTERISKS\*\* HAVE BEEN USED TO HIGHLIGHT REVISIONS.**

**SUBJECT:**

Service Bulletin/RRT 21-001-15/15-003 Superseded By Customer Satisfaction Notification (CSN) R01

**OVERVIEW:**

Refer to service procedures outlined in CSN R01.

**MODELS:**

2014-2015	(KL)	Jeep Cherokee
2015	(UF)	Chrysler 200

**DISCUSSION:**

Vehicles that have not had the RRT performed will now be covered under Customer Satisfaction Notification (CSN) R01 and should follow all service procedures and labor times outlined in the CSN.

**POLICY:**

Information only.