

Herndon, December		
Mr.		
Name		
Street		
City State Zip Code		
,		

Automobili Lamborghini America LLC

Headlamp System Update - Your Lamborghini Aventador with chassis number: «VIN»......

SAFETY RECALL NOTICE - NHTSA CAMPAIGN NUMBER 12 V-561

Dear Sir/Madam,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Automobili Lamborghini S.p.A. has decided certain Lamborghini Aventador model year 2012 vehicles fail to conform to the requirements of Federal Motor Vehicle Safety Standard No. 108 Lamps, Reflective Devices, and Associated Equipment.

WHAT WE WILL DO

We will update the headlamp system free of charge to enable vertical headlamp aiming and disable horizontal one.

WHAT YOU SHOULD DO

Please contact your Lamborghini dealer as soon as possible to arrange a service date and so the dealer may order the necessary parts for the repair. Instructions for making this correction have been sent to your dealer and the parts are available. The labor time necessary to perform this service correction is approximately 2 hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your vehicle.



Your Lamborghini dealer is best equipped to obtain parts and provide service to ensure that your vehicle is corrected as promptly as possible. If, however, you take your vehicle to your dealer on the agreed service date, and they do not remedy this condition on that date or within three (3) days, we recommend you contact the Lamborghini customer service (Automobili Lamborghini America LLC) by calling 1-866-681-6276 (from 9.00am to 5.00pm East Coast time), emailing USAServiceDepartment@lamborghini.com, or faxing ,1-703-364-7015.

After contacting your dealer and Automobili Lamborghini America LLC and you are still not able to have the noncompliance remedied without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

Please bring this letter and your Service Booklet with you when you visit the dealer, so that we can make all necessary entries.

Federal law requires any lessor who receives a notification of a determination of a safety-related defect or noncompliance pertaining to any leased motor vehicle shall send the notice to the lessee within 10 days.

If you are no longer owner of this vehicle, please provide us with any contact information so we may contact the new owner.

We are sorry to cause this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Yours sincerely,

Michael Lock Chief Operating Officer Automobili Lamborghini America LLC Renè Sueltzner Head of After Sales Automobili Lamborghini America LLC

Remé Suettern



Automobili Lamborghini America LLC Customer Service and Spare Parts

Fax: +1-703-364-7015

E-mail: USAServiceDepartment@lamborghini.com

REPLY SHEET: LP 700-4 Headlight

Vehicle Chassis No.:
Vehicle cannot be checked because it has been:
□ scrapped □ stolen
□ Stolen
□ sold to a domestic buyer
□ sold to an overseas buyer
to following new address:
Name
Name:
First Name:
Street:Nr
ZIP Code: City:
Country
I Allatav