

SSM 47342	2018 F150 vehicles excluding Raptor built at Dearborn Truck Plant on or after 26-Feb-2018 and at Kansas City Assembly Plant on or after 10-Mar-2018 have the AAT sensor located in the right exterior mirror. The AAT sensor was relocated from the front grill/fascia area. The AAT sensor is serviced separately from the mirror. Refer to Ambient Air Temperature Sensor GSB G0000178 for additional information. The Workshop Manual (WSM) is in the process of being updated for non-Raptor vehicles. The sensor location on Raptor vehicles has not changed
--------------	---