

SSM 48718 - 2020 Transit - No Step Well Pad On Passenger Sliding Door Step - Built On Or Before 16-Dec-2019

Some 2020 Transit vehicles with no rear floor covering built on or before 16-Dec-2019 are manufactured without the step well pad on the passenger sliding door step. The vehicle is not misbuilt. Do not submit a claim for this condition.