

Center Rear Seat Belt Buckle Installation Is OK

AFFECTED VEHICLES

All 2014–**16** five-passenger models

EDITOR'S NOTE: This article replaces the one posted in **October 2014**. Changes are highlighted in **yellow**.

On some five-passenger models, at first glance, the center rear seat belt buckle may look like it isn't installed right (it looks crossed with the left outer buckle). Actually, it's OK. The outer buckles are intentionally mounted **inboard** of the center belt and buckle to give the passengers on either side more room to work their seat belts.



Don't unbolt the lower anchor plates to uncross the seat belts. Such a change in the belts' configuration, could affect their level of protection.