

NUMBER: 23-025-15

GROUP: Body

DATE: July 08, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Rear Door Glass Stain

OVERVIEW:

This bulletin involves removing stains from the rear door glass.

MODELS:

2015 (B1)

Jeep Renegade (Brazil Only)

NOTE: This bulletin applies to vehicles built on or before May 09, 2015 (MDH 0509XX) with sales code XL9 - Portuguese (Brazil) Language.

DISCUSSION:

Some customers may describe stains on the rear door glass as shown in (Fig. 1). This bulletin contains the procedure for removing stains from the glass.



Fig. 1 Glass Stain

PARTS REQUIRED:

Qty.	Part No.	Description
AR	NPN	3M Finesse-it Finishing Material 81235 (or equivalent)

NOTE: Each 1 liter bottle of 3M Finesse-it finishing material 81235 will service approximately 16 vehicles.

SPECIAL TOOLS/EQUIPMENT REQUIRED:

NPN	Rotary Buffer equipped with Wool Pad	
-----	--------------------------------------	--

NOTE: The rotary polish machine is a non-reimbursable shop tool.

GLASS STAIN REMOVAL:

1. Position the vehicle in an area with good illumination.

NOTE: Protect the vehicle interior and door panel from finishing material during the cleaning and polishing process.

- 2. Clean the window area with a microfiber cloth on the inside and outside of the glass.
- 3. Using circular movements, apply the 3M Finesse-it finishing material (or equivalent) to the inside and outside of the glass (Fig. 2).



Fig. 2 Apply Glass Polishing Product

-3- 23-025-15

NOTE: A rotary buffer equipped with wool pad is required for the polishing process in order to raise the glass surface temperature for complete glass stain removal.

4. Polish the glass stain area using a rotary buffer equipped with wool pad(Fig. 3).



Fig. 3 Polish Glass With Rotory Buffer

5. Use a microfiber cloth to remove all product residue (Fig. 4).



Fig. 4 Remove Residue Using Microfiber Cloth

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-30-05-90	Polish Glass - One Or Both Rear Doors (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.3 Hrs.

FAILURE CODE:

ZZ Service Action

PART REIMBURSEMENT DETAIL:

Part No:	Description
NPN	1/16 Of 3M Finesse-it Finishing Material 81235 One Liter Bottle

NOTE: This part number is for reimbursement only and will need to be claimed for 1/16 the value of 3M Finesse-it finishing material 81235 one liter bottle or it will be rejected. If this is a non-MOPAR part or product, a copy of the invoice showing the purchase of the non-MOPAR part or product needs to be attached to the reimbursement claim.