



## Front Door Glass Squeaks When Going Up or Down

### SYMPTOM

The left or right front door glass squeaks when going up or down.

### PROBABLE CAUSE

The glass is rubbing on its inner weatherstrip.

### CORRECTIVE ACTION

Replace the door glass inner weatherstrip.

### PARTS INFORMATION

Left-Front Door Glass Inner Weatherstrip:

P/N 72375-SEA-013

Right-Front Door Glass Inner Weatherstrip:

P/N 72335-SEA-013

### TOOL INFORMATION

KTC Trim Tool Set: T/N SQJATP2014

### WARRANTY CLAIM INFORMATION

**In warranty:** The normal warranty applies.

OP#	Description	FRT
8351A4	Replace the left-front door glass inner weatherstrip.	0.4
8361A4	Replace the right-front door glass inner weatherstrip.	0.4

Failed Part: P/N 72335-SEA-013

Defect Code: 03001

Symptom Code: 04205

Skill Level: Repair Technician

**Out of warranty:** Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Parts and Service Manager or your Zone Office. You must request consideration, and get a decision, before starting work.

### DIAGNOSIS

1. Lower the affected door glass two-thirds of the way down.
2. Slip a piece of paper or thin cardboard between the glass and the inner door panel weatherstrip.
3. While holding the paper in place, move the glass up and down.
  - If the squeak is gone, go to REPAIR PROCEDURE.
  - If the squeak is still there, remove the door panel and continue with normal diagnosis for run channel or regulator noise.
  - If caused by the inner weatherstrip, the squeak may go away after repeated operation of the door glass but return after several days.
  - Do not replace the regulator or the run channel unless the squeak is still there when the glass is moved up and down with the inner door panel removed.

### REPAIR PROCEDURE

Remove the front door panel, and replace the door glass inner weatherstrip:

- Refer to page 20-7 of the *2004–08 TSX Service Manual*, or
- Online, enter keywords **DOOR PANEL**, and select **Front Door Panel Removal/Installation** from the list.