

L73X-A.03.16	To: Subject: Date: Pages	Official After Sales Network Warranty booklet integration. June 6,2016 2	
---------------------	---	---	---

Campaign code.L73X-A.03.16**Campaign description.**Warranty booklet integration**Model.**Aventador Coupè. Aventador Roadster.**Model year.**2015 and 2016**Special or Limited Versions.**All.**Markets.**USA only.**VIN identification**From **FLA03655** to **GLA04655**.

3655->3820	3821->4217	4234->4326	4331->4452	4456->4572	4574->4655
...3655	...3821	...4234	...4331	...4456	...4574
...3698	...3832	...4236	...4334	...4457	...4575
...3707	...3835	...4238	...4335	...4459	...4576
...3712	...3839	...4247	...4337	...4461	...4579
...3717	...3851	...4251	...4341	...4463	...4581
...3724	...3859	...4253	...4344	...4465	...4582
...3727	...3862	...4255	...4348	...4467	...4583
...3730	...3865	...4261	...4350	...4468	...4586
...3736	...3867	...4262	...4352	...4469	...4588
...3737	...3870	...4264	...4357	...4471	...4589
...3738	...3883	...4265	...4365	...4474	...4591
...3744	...3889	...4267	...4366	...4477	...4595
...3746	...3895	...4268	...4367	...4479	...4596
...3750	...3900	...4270	...4368	...4486	...4597
...3751	...3904	...4273	...4369	...4488	...4598
...3752	...3906	...4274	...4371	...4490	...4602
...3754	...3909	...4276	...4373	...4493	...4603
...3759	...3911	...4279	...4375	...4501	...4604
...3762	...3952	...4280	...4385	...4511	...4613
...3767	...3971	...4285	...4387	...4513	...4615
...3775	...3980	...4286	...4392	...4515	...4617
...3777	...3999	...4287	...4394	...4517	...4621
...3779	...4010	...4289	...4400	...4526	...4623
...3780	...4033	...4291	...4403	...4529	...4625
...3781	...4041	...4292	...4409	...4531	...4628
...3784	...4045	...4296	...4410	...4532	...4637
...3789	...4050	...4298	...4413	...4544	...4638
...3791	...4056	...4301	...4415	...4546	...4640
...3792	...4079	...4303	...4422	...4551	...4645
...3793	...4155	...4304	...4427	...4553	...4647
...3798	...4156	...4306	...4431	...4555	...4648

...3800	...4162	...4308	...4432	...4556	...4650
...3801	...4182	...4311	...4435	...4559	...4652
...3805	...4190	...4313	...4438	...4560	...4655
...3809	...4194	...4319	...4440	...4563	
...3810	...4199	...4321	...4444	...4565	
...3817	...4201	...4322	...4449	...4566	
...3818	...4210	...4324	...4451	...4568	
...3820	...4217	...4326	...4452	...4572	

Warning: some vehicles included in this VIN range may not be involved, so check carefully on the Lamborghini WEB Portal (at the section named VIN Info) if the cars in your workshop or in your dealer stock are involved before performing any other operation.

Information to the field

As a result of continuous product monitoring, Automobili Lamborghini Spa found that on some US vehicles the warranty booklet is missing of the pages which detail the customer protection information.

Field solution

Affix the integration booklet at the warranty one.

Spare parts.

P/N	Description	Q
4T0012716	Warranty integration booklet	1

Replaced parts management (when applicable).

Store properly and tagged the parts replaced with bar code form for their identification during Area Manager visits.

Labour time

Time for sticking the integration biooklet : **0.2 hour..**

Warranty Claim instructions


To claim the reimbursement log into the warranty system management on the Lamborghini Portal and consults the manual "W.Claim " available on the portal for the download .

Select the desired campaign and go on with the claim insertion, read carefully the windows message content and choose the option button corresponding to the operation performed .

Rev.01	The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.	1/2
--------	---	-----

L73X-
A.03.16

To: Official After Sales Network
Subject: Warranty booklet integration.
Date: June 6,2016
Pages: 2



On the base of the chosen option the reimbursement will be:

- OPTION B,
 manpower: 0.2 hours
 spare parts: 4T0012716.



ATTENTION!

Attach all documents produced during the vehicle visit that show evidence of the work performed such as repair order, software protocols or acquisitions...etc.; the lack of one or more of those, may deny the reimbursement.

Remember to fill all data in the section “Service and Recall Campaign” in the Warranty booklet of the vehicle as shown below.

Necessary tools/material.

P/N	Description	Q
-		

Instructions:


1. Take the warranty booklet out from the glove box and place it on suitable desk; open the warranty booklet at the last page.



2. Remove the paper band, which protects the adhesive tape, from both sides of the booklet furnished as integration.



3. Let the adhesive sides adhere to the warranty booklet pages and put a weight over the booklet leaving the glue to properly bond for at least 2 minutes.



4. Put the warranty booklet back in the glove box.