

# **Technical Journal**

#### TITLE:

# Gurgling sound from sunroof area, while driving in the rain

REF NO: TJ 34532.1.0	ISSUING DEPARTMENT: Technical Service	]	ARKET: s and Canada
3 US 7	PARTNER: '510 Volvo Car USA	ISSUE DATE: 2019-04-29	STATUS DATE: 2019-05-03
FUNC GROUP: 8369	FUNC DESC: Miscellaneous	Page	1 of 7

"Right first time in Time"

#### **Attachment**

File Name	File Size
TJ 34532 Gurgling noise Audio.mp3	0.4733 MB
TJI-516846-1 1 0 en-US.pdf	1.1511 MB

#### **Vehicle Type**

Туре	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536						2019-9999		0000329-9999999	201746-999952

## **CSC** Customer Symptom Codes

Code	Description
ZB	Sun/moon/convertible roof/Wind noise

## **VST** Operation Number

VST Operation Number	Description
98728-2	Sunroof drainage hose extention acc. to TJ34532

### **DTC** Diagnostic Trouble Codes

#### **Text**

# **Technical Journal 34532.1.0**



#### **DESCRIPTION:**

Gurgling sound from sunroof area, while driving in the rain, see attached <u>mp4-file</u>, noise is coming from the sunroof /A-pillar area while driving in the rain. The noise is louder when the sunshade is open. please follow the description under "service".

#### **SERVICE:**

In certain conditions, wind turbulence may prevent the water from drain properly.

Extend the sunroof front drain hoses by following the attached method.

#### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8369.

To view TJ attachment continue to next page. This TJ has one attachment and one sound file.

Page 2 of 7 2019-05-03



# Volvo Car Customer Service TJ Instruction VCC-516846-1

Title	Sunroof draining hose	Page	1 (5)
Action	Adjustment	Operation number:	98728-2

Issue	Date	Reason
1	2019-04	First issue


### **Affected vehicles**

Model year	Model
2019	XC40

# **Materials**


Materials	Qty.	Part No.	Notes
Hose	1.0	31371480	


#### **Color symbols**



Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.

- Used for focused component, the component with which you will do something.
- 2. Used as extra colors when you need to show or differentiate additional parts.
- Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
- 4 . Used when the component is not fully removed from the vehicle but only hung to the side.
- 5. Used for standard tools and special tools.
- 6 . Used as background color for vehicle components.





#### Removal


Remove the plenum cover, refer to:
Removal, replacement and installation
8 - Body and interior
82 - Bonnet (Hood), front end, wings,
door sill
823 - radiator grille

Remove the wiper mechanism, windscreen , refer to:


Removal, replacement and installation
3 - Electrical system
36 - Other electrical equipment
363 - cleaner

Remove woofer, front, refer to:
Removal, replacement and installation
3 - Electrical system
39 - Media, communication and
navigation
395 - radio equipment


# Installation




Left-hand side




Left-hand side




Left-hand side



Right-hand side



Right-hand side



Right-hand side