

# **Preliminary Information**

## PIP5654 10L90 10L80 10 Speed Automatic Transmission Valve Body Part Unique Number PUN May Contain the Letter O Or The Number 0

#### Models


Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Transmissions:
Cadillac	CT6 Models	2019	All	All	LGW LGX LSY LTA	MHS MHW
Cadillac	Escalade Models	2018 - 2019	All	All	L86	MF6
Chevrolet	Camaro	2017 - 2019	All	All	LT1 LT4	MF6 MGL
Chevrolet	Silverado 1500 New Model	2019	All	All	L87	MQB
Chevrolet	Suburban RST	2019	All	All	L86	MF6
Chevrolet	Tahoe RST	2018 - 2019	All	All	L86	MF6
GMC	Sierra 1500 New Model	2019	All	All	L87	MQB
GMC	Yukon Denali Models	2018 - 2019	All	All	L86	MF6

Involved Region or Country	North America
Condition	Some customers may comment on the operation or performance of the 10L80 or 10L90 transmission.
Cause	Technician's may replace the valve body to address these concerns.

#### **Correction:**

If the valve body is replaced the dealer technician may find that software may not accept the Part Unique Number (PUN) during the characterization procedure.

Please be aware that the PUN may contain the letter O or the number 0 as shown in the picture below.



Call Out 1

The number 0.

Call out 2

The letter O.

### **Version History**

Version	1
Modified	06/13/2019 - Created on.

















GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.