
February 6, 2021

Version 2

Center Display Unit Stays On with Ignition Turned to OFF and Door Open (Replaced by 20-031, Popping/Crackling from the Speakers; Display Blank, dated February 6, 2021)

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by “do-it-yourselfers,” and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.