WORK DESCRIPTION FOR FIELD MEASURE

Code: 21P5498204

Version: 2.0

Retrofit rubber mounting for mobile phone cradle in front center console Model 223 with code 897

i • Code 897 corresponds to WIRELESS PHONE CHARGING IN THE FRONT.

Work procedure

1. Retrofit rubber mounting (A) for mobile phone cradle in front center console (Figure 1).



Figure 1

Parts

Quantity	Designation		Part no.	
1	Rubber mat		A 223 823 05 0	0

i Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-0751	Retrofit rubber mounting for mobile phone cradle in front center console	0.1 h	54 982 04

Mercedes-Benz Global Service & Parts